### STANDARD PART LIST (M97 2006 – 2008, not for M96!!)

Part name	Qty	Part number	genuine/OEM	Cost (ea)	Cost (ext)	Source	Comment
Head gasket	2	100-904-211	OEM (M97.1 SET)	\$408.95	\$408.95	eeuroparts.com	complete gasket and seal set, Europarts states it's
Main oil pump housing gasket	1		,	,	'	'	OEM but does not list manufacturer, likely Elring.
Thermostat gasket	1	1					
Upper radiator hose gasket	1	1					
Upper case water jacket	1	1					
Water bypass gasket	1	1					
Water housing gasket	1	1					
Water outlet gasket	1	1					
Water pump gasket	1	1					
Water temp sensor gasket	1	1					
Air injection cut-off valve gasket	1	1 1					
Crankcase lid gasket	<u> </u>	1 1					
Secondary Air Injection Pipe Bracket Gasket	1						
Secondary Air Injection Pipe Gasket (on Crankcase)	1						
Case bolt o rings	4	1					
	6	<del> </del>					
Chain rail bolt o ring	1						
Dipstick tube o ring		4					
Inner spark plug tube o ring	6						
Oil pump housing o ring	2	1					
Outer spark plug tube o ring	6						
Pick up tube o ring	1	1					
Scavenge pump o ring	2	]					
Oil fill tube o ring	1						
Large heat exchanger seal	2	]					
Oil drain plug seal	1	]					
Oil level sensor seal	1	]					
Oil pressure switch seal	1	1					
Small heat exchanger seal	2	1					
Solenoid seal	4	1					
Front seal	1	1					
Rear main seal	1	<del>1</del>					
AOS – Primary	<u> </u>						Non-OEM from Pelican available
(for 3.8, 3.6 is 996-107-026-52)	1	997-107-038-01	genuine	\$225.17	\$225.17	Porschepartsnow.com	(Febi Bilstein for \$91)
AOS - Secondary	2	997-107-138-00	genuine	\$66.95	\$122.44	Porschepartsnow.com	, , ,
Cam sprocket bolts	8	PAF-008-124-A	genuine	\$3.01	\$24.08	Porschepartsnow.com	
Camshaft gear bolt	2	987-105-254-00	genuine x2	\$18.54	\$37.08	Porschepartsnow.com	reuse unless worn
Camshaft shim washer	2	996-105-203-00	genuine x2	\$23.90	\$47.80	eeuroparts.com	
Carrier bolts	14	996-101-115-62	genuine x14	\$6.93	\$97.02	Porschepartsnow.com	ARP are \$130 from LNE
Case bolts	25	9A7-008-125-00	genuine x25	\$0.75	\$18.75	eeuroparts.com	
Crush washer	1	900-123-106-30	genuine	\$1.61	\$1.61	Porschepartsnow.com	
Head bolts	24	996-104-180-58	OEM x24	\$8.20	\$196.80	eeuroparts.com	reuse unless worn
Large cam plug	2	Could not find	OLIVI XZ4	ψ0.20	\$150.00	ccuroparts.com	I Cusc unicss worn
Exhaust Lifter	12	996-105-041-72	OEM (INA 4200104100)	\$15.92	\$191.04	eeuroparts.com	reuse unless worn
Lower case water jacket	1	included with thermostat	CLW (1147 4200 104 100)	ψ1J.5Z	\$131.04	ccuroparts.com	reade arriedd WOITI
LOWGI GUSE WATEI JACKET		moraded with themilostal					Possible-OEM full set from Pelican for \$328
Main bearing	14	996-101-209-04	genuine x14	\$34.95	\$489.30	eeuroparts.com	(Kolbenschmidt 996-101-209-04-SET-M173)
Oil cooler	1	997-107-025-02	OEM (Mahle CLC61000P)	\$173.95	\$173.95	eeuroparts.com	reuse unless worn
Oil drain plug	1	900-219-009-30	OEM (900-219-009-30)	\$2.92	\$2.92	eeuroparts.com	Succe annous worn
Oil drain plug Oil filter	1	996-107-225-60	OEM (Mann HU7195X)	\$8.75	\$8.75	eeuroparts.com	
Rod bearing	12	996-107-225-60	genuine x12	\$9.30	\$111.60		
	12	996-103-121-62	Genuine x12 OEM x12	\$9.30	\$111.60	eeuroparts.com	
Rod bolts						eeuroparts.com	
Small cam plug	4	996-104-215-54	OEM (Elring 692290)	\$6.91	\$27.64	eeuroparts.com	
Spark plug	6	999-170-223-90	OEM (Bosch FGR5KQE0)	\$5.80	\$34.80	eeuroparts.com	
Tensioner paddle wear pin	1	996-105-197-00	genuine	\$44.10	\$44.10	Porschepartsnow.com	
Tensioner washer	4	900-123-147-30	genuine	\$1.08	\$4.32	Porschepartsnow.com	
Thermostat	1	996-106-013-61	OEM (Wahler 424971D)	\$49.95	\$49.95	eeuroparts.com	Comes with housing/jacket, 71 deg opening
Thrust bearing	2	996-101-129-52	genuine	\$13.77	\$27.54	eeuroparts.com	Alternate: 0PB-105-638 (may be superseded)
Timing chain	2	996-105-152-01	OEM (IWIS 50026971) x2	\$42.95	\$85.90	eeuroparts.com	Says BMW part but IWIS PN same for M97
Timing chain (IMS large sprocket)	1	996-105-171-58	genuine	\$129.60	\$129.60	Porschepartsnow.com	
Timing chain guide (IMS large sprocket)	1	996-105-166-51	genuine	\$41.01	\$41.01	Porschepartsnow.com	
Guide rail (left lower, right lower)	2	996-105-168-04	genuine x2	\$35.35	\$70.70	Porschepartsnow.com	
Timing chain rail (tensioner side 1-3)	1	996-105-156-00	genuine	\$38.99	\$38.99	Porschepartsnow.com	
Timing chain rail (tensioner side 4-6)	1	996-105-158-01	genuine	\$43.20	\$43.20	Porschepartsnow.com	
Timing chain rail (1-3)	1	996-105-054-01	genuine	\$66.12	\$66.12	Porschepartsnow.com	
	1			\$38.95			
Timing chain rail (4-6)	1	996-105-164-00	genuine		\$38.95	eeuroparts.com	
Timing chain rail pad (for IMS tensioner)		996-105-195-00	genuine	\$24.76	\$24.76	eeuroparts.com	
Valve cover bolts	54	999-385-003-01	genuine	\$2.65	\$143.10	Porschepartsnow.com	
				SUM	\$3,069.46	1	I .
			SUM w/o red with g	UM w/o red	\$2,470.59		

# PREMIUM PARTS LIST FOR M97 (ADDITIONAL)

D. d	-			10 1/ )	0 1/ 0		10
Part name	Qty	Part number	genuine/OEM	Cost (ea)	Cost (ext)	Source	Comment
Air injection cut-off valve gasket	1	included in gasket set					
Cam sensor	2	997.606.106.03	OEM (Bosch 0232103092)	\$23.82	\$47.64	eeuroparts.com	reuse unless worn
Chain Tensioner - IMS	1	996-105-180-58	genuine	\$75.30	\$75.30	Porschepartsnow.com	reuse unless worn
Chain Tensioner - Lower Left	1	996-105-186-02	genuine	\$102.35	\$102.35	Porschepartsnow.com	reuse unless worn
Chain Tensioner - Upper Right	1	996-105-188-02	genuine	\$121.07	\$121.07	Porschepartsnow.com	reuse unless worn
Crank sensor	1	986-606-112-04	OEM (Bosch 0261210248)	\$52.95	\$52.95	eeuroparts.com	reuse unless worn
Knock sensor	2	0PB-905-377-B	OEM (Bosch 0261231173)	\$23.24	\$46.48	Pelican Parts	reuse unless worn
Oil fill tube	1	997-107-131-00	genuine	\$78.84	\$78.84	Porschepartsnow.com	reuse unless worn
Oil level sensor	1	996-606-150-01	genuine	\$83.00	\$83.00	Porschepartsnow.com	reuse unless worn
Oil pressure switch	1	996-606-203-03	genuine	\$70.90	\$70.90	Porschepartsnow.com	reuse unless worn
Secondary Air Injection Pipe Bracket Gasket	1	included in gasket set					
Secondary Air Injection Pipe Gasket (on Crankcase)	1	included in gasket set					
Solenoid (variable valve timing)anos)v	4	996-105-303-06 (front) 996-105-301-04 (rear*) 997-105-301-00 (rear*)	genuine x2 Genuine x2	\$202.18 \$194.79	\$793.94	Porschepartsnow.com	reuse unless worn * Note: PN on rear Solenoid changed partway through the M97 run, need to check engine number
Vent hose - primary oil separator to engine	1	997-107-145-02	OEM (4008292)	\$60.95	\$60.95	eeuroparts.com	reuse unless worn
Vent hose - primary to secondary oil separator (cyl. 1-3)	1	997-107-143-01	OEM (4008293)	\$44.95	\$44.95	eeuroparts.com	reuse unless worn
Vent hose - primary to secondary oil separator (cyl. 4-6)	1	997-107-146-03	OEM (4008291)	\$103.95	\$103.95	eeuroparts.com	reuse unless worn

## Sheet1

Vent line for primary oil separator (lower							
fitting)	1	997-106-024-02	genuine	\$50.76	\$50.76	Porschepartsnow.com	reuse unless worn
							eeuroparts.com also has a Gates 42579 WP listed as
Water pump	1	997-106-011-06	OEM (Pierburg 728015020)	\$189.95	\$189.95	eeuroparts.com	OEM quality for \$132
Water temperature sensor	1	996-606-410-00	genuine	\$31.95	\$31.95	eeuroparts.com	reuse unless worn
				SUM	\$1,954.98		
			SUM w/o red		\$189.95		
			SUM w/o red with green option		\$131.95		

- Legend on cost column:
   Black: part should be replaced
   Red: part may be reused if not damaged or worn excessively
   Green: No OEM option found but other sources shown in comments could be considered

- Updates:
   Secondary AOS is quantity 2 not 1
   Valve solenoid (rear) may change mid way through M97 build to 997-105-301-00