



The new Cayenne models. Visit your authorized Porsche dealer now to learn more.

PORSCHE
 Porsche Cars North America, Inc.
 980 Hammond Dr., Suite 1000
 Atlanta, Georgia 30328

PERMIT
 FIRST CLASS
 U.S. POSTAGE
 PAID
 ATLANTA GA
 PERMIT NO. 3828

Warranty Extension Notification:

Vehicle
 Identification
 Numbers:
 10


WPIA/



*****AUTO**3-DIGIT 949 TB7 P1



NO POSTAGE
 NECESSARY
 IF MAILED
 IN THE
 UNITED STATES



BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO. 26231 ATLANTA, GA

POSTAGE WILL BE PAID BY ADDRESSEE

PORSCHE CARS NORTH AMERICA, INC.
 980 HAMMOND DRIVE NE
 SUITE 1000
 ATLANTA, GEORGIA 30328-8187



1029377

Warranty Extension Notification:



PORSCHE

Porsche is providing an extended warranty program to owners of 2003-2006 model year Cayenne, Cayenne S, Cayenne Turbo and Cayenne Turbo S vehicles. Your vehicle is affected by this program.

What is the concern and what should you do?

Through ongoing quality data analysis, Porsche has identified a concern with the performance of the ignition coils on the vehicles identified above. The concern relates to various problems with the ignition coil that result in illumination of the "Check Engine" warning indicator. Should you notice the illumination of this indicator, contact your preferred Porsche dealer without delay, quoting your vehicle identification number located at the beginning of this letter.

What will Porsche and Porsche dealers do?

Porsche is extending the warranty on the improved ignition coils with the part number 955 602 101 04 (and successor part numbers), for the condition stated above, i.e. for 4 years or 50,000 miles from the first date of the installation of the improved parts, whichever occurs first. During the extended warranty period, should your Porsche dealer diagnose your vehicle with the concern noted above, the ignition coil will be replaced at no charge to you under the terms of this extended warranty program. Porsche recommends you retain a copy of this letter in your vehicle's owner's literature wallet.

What should you do if you have already paid to have this repair completed?

If you meet all the following requirements, you are eligible to receive reimbursement:

1. You own or have owned a 2003-2006 model year Cayenne model.
2. You have paid to replace the ignition coil(s) for the concern described above.
3. The repair was performed before the date of this letter and vehicle mileage did not exceed 100,000 miles at the time of replacement.
4. You have an original or legible copy of the paid repair order or invoice showing:
 - Your name and address at the time of the repair
 - A description of the concern reported
 - Itemized parts and labor charges
 - The vehicle model and year and the vehicle identification number
 - The repair date
 - Repair mileage
 - Name and address of the authorized Porsche dealer or licensed repair facility

If you have all of the above information, please forward it to the following address for reimbursement of your claim:

Porsche Cars North America, Inc.
980 Hammond Drive, Suite 1000
Atlanta, GA 30328
Attn: Customer Commitment Department

Please ensure that you retain copies of all of the paper work supporting this claim. If the repairs were performed by anyone other than an authorized Porsche dealer, the amount of reimbursement may be limited by the amount you would have been charged to have your vehicle repaired by an authorized Porsche dealer.

Moved or no longer own the vehicle?

If you are no longer the owner of this vehicle, Porsche would greatly appreciate the name and address of the new owner (if known); please fill out and return the enclosed return postage-paid card.

If you have concerns

If you have any questions or concerns that your local Porsche dealer cannot resolve, please contact the Porsche's Customer Contact Center at 1-800-PORSCHE, and one of our Customer Commitment Specialists will be happy to assist you. We sincerely regret any inconvenience this Customer Notification may cause, and hope you understand our interest in performing this work promptly so that you can be satisfied with your Porsche automobile. Please accept our apologies for this unplanned service visit.

Sincerely,

Tom Quinn
Vice President, After-Sales
Porsche Cars North America, Inc.



Based on your location, sales and service history, our records indicate your closest Porsche Dealership is:

Sorren Porsche
(415)380-8000
900 Redwood Hwy
Mill Valley, CA 94941-2345

If you no longer own this automobile or your address is different from that shown below, please complete this reply card, detach and return. Thank you for your assistance.

My correct address is: or I sold this vehicle to:

Last Name										First Name										Initial	
Number										Street										Postal Code	
City										Province											

Vehicle sold:

Vehicle totaled/scrapped:

Vehicle reported stolen:

Vehicle has been exported:

Month Day Year

Please print and give complete information.

VIN #: WP1AC

