

PCCB Rotor Check | VAS 6813

Tool S/N: CT91-165-0230


Functional Test Deviation: 0.5 CQ

Technician: Mike Squatrito

Date: 5/22/23

VIN: Loose Rotors

Mileage: Unknown



	Meas. Point	New Figure	Wear Limit	Measured
--	-------------	------------	------------	----------

	Part #	1	47 58	44	57
--	---------------	---	------------------	----	----

	991.351.409.86	2	57	43	56.1
--	-----------------------	---	----	----	------

	Rear Left	3	56	42	55.3
--	------------------	---	----	----	------

	Part #	1	47	35	46.3
--	---------------	---	----	----	------

	991.351.409.86	2	47	35	46.6
--	-----------------------	---	----	----	------

	Rear Right	3	49	37	48.1
--	-------------------	---	----	----	------