## 955 Maintenance History

D.I.	Lauren .		Paradallar	D. d.	Labor		aintenance His		D. d. die		T-1-101	Miles Deles	01	Man A Carret		
Date	Location	Mileage	Description	Parts	Labor	Shop Misc Charge Sub Total De Supplies			Deductions	Deductions Tax Total Spent		Miles Driven	Cost per mile	Matt \$ Spent	Matt Miles Driven	Matt Cost per mile
								RUN	INING TO	OTAL>	\$16,677.38	93,000	\$0.18	\$4,360.42	41,950	\$0.10
15 Jul 08	The Collection (Porsche Coral Gables)	6,167	Driver side seat back remove and replace; passenger seat back rest R&R 10,000 mile service interval performanced oil filter change; fuel system maintenance performed	\$149.00	\$377.45			\$526.45		\$36.84	\$563.29					
16 Jan 09	The Collection (Porsche Coral Gables)	9,774	AC control panel replaced; roof liner removed and reintalled; driver side door door adjusted, tightened lower hinge; 2-year brake flush; Dent Wizard for dent removal	\$46.02	\$270.00		\$129.99	\$446.01		\$31.20	\$477.21					
21 May 09	The Collection (Porsche Coral Gables)	14,048	Replaced AC pressure line oring; charged system; high pressure line to rear AC replaced					\$0.00			\$0.00					
23 Jul 09	The Collection (Porsche Coral Gables)	15,700	Reprogrammed 2 remotes; cornering ligh bulbs replaced; Chip Wizard scratch repair; headlight adjustment; replace wiper blades; front underbody panel replaced	\$232.49	\$145.00		\$140.15	\$517.64		\$36.21	\$553.85					
4 Nov 09	Tires Plus	18,201	Bridgestone Tires with Uni-T Package; alignment	\$919.92	\$138.99		\$7.56	\$1066.47		\$74.66	\$1141.13					
4 Nov 09	Tires Plus	18,201	Front Brake Pads replaced; braking disc sensors	\$311.52	\$80.00		\$4.80	\$396.32		\$27.75	\$424.07					
16 Jun 10	The Collection (Porsche Coral Gables)	23,565	AC Checked; Brakes checked; Right corner light bulb replaced; 2-year maitenance Cayenne; oil/liter changed; pollen filter; 20,000 mile service interval performed; Cayenne fuel maintenance service; brake flush	\$262.90	\$564.93		\$39.00	\$866.83		\$60.65	\$927.48					
	The Collection (Porsche Coral Gables)		1-year maintenance Cayenne V8; oil service; Cayenne fuel maintance service; replace driver side rear tail light; replace front pads, rotors and sensors; replace rear pads, rotors and sensors	\$1411.19	\$1115.66		\$10.00	\$2536.85		\$177.56	\$2714.41					
	Larry's Service Center		R134 Freon Recharge 16oz	\$32.00	\$49.00			\$81.00		\$5.67	\$86.67					
	Martino Tire	38,183	Ventus ST RH06 Hankook 275/40R20/XL; Nitrogen fill; 4-wheel alignment	\$850.00	\$196.96		\$15.76	\$1062.72		\$52.94	\$1115.66					
4 Dec 12	The Collection (Porsche Coral Gables)	38,241	Coolant pipes, all associated parts replaced/cleaned/ reinstalled; Multi-point inspection; 4-year maintenance Cayenne V8; 40k mile service; brake fluid flush; nitrogen tire fill, fuel service maintenance; car wash	\$935.31	\$1091.49		\$39.00	\$2065.80		\$144.58	\$2210.38					
21 Feb 13	The Collection (Porsche Coral Gables)	39,981	Replaced catalytic converters, exhaust pipes, gaskets; replaced left corner bulb and right front fog light bulb; replaced driveshaft; replaced e-brake pedal shock; replaced rear hatch shocks; replaced rear glass shocks	\$1316.30	\$870.00		\$15.00	\$2201.30	-\$327.95	\$131.11	\$2004.46					
	Martino Tire		Tire Balance; Check alignment; Check air pressure					\$0.00		\$0.00	\$0.00					
-	Martino Tire		TPMS Sensor valve & reprogram	\$39.00	\$49.00		\$3.92	\$91.92		\$6.43	\$98.35					
	Porsche of Hilton Head		Cayenne Complete Oil Service Performed	\$114.27	\$189.45		\$25.38	\$329.10	-\$30.37	\$9.15	\$307.88					
30 Dec 14	Self	56,569	60K MILE SERVICE: Replaced 8x Ignition Coil (948-602-104-21); Replaced 8x Spark Plugs (999-170-218-90); Replaced Cabin Air Filter (955-572-219-10); Replaced front wiper blades (955-628-939-03); Replaced Engine Torque Damper (955-375-101-13)	\$497.34	\$0.00		\$13.38	\$510.72			\$510.72					
2 Jan 15	Self	56,650	Replaced Battery (VW 000-915-105-DL)	\$208.50	\$0.00		\$13.55	\$222.05			\$222.05					
23 Jan 15	Self	57,335	Replaced Gas Cap (955-201-241-21)	\$21.27	\$0.00		\$9.88	\$31.15			\$31.15					
29 Mar 15	Self	61,382	Cayenne Complete Oil Service Performed: Replaced 2x Aluminum Washer (900-123-106-30); Replaced 1x Oil Drain Plug (900-219-020-31); Replaced 1x Oil MAHLE OIM Filter Kit (996-107-225-53); Replaced 9 qts Mol1 0w-40 Replaced Engine Air Filter (955-110-131-10)	\$98.62	\$0.00		\$0.00	\$98.62		\$3.60	\$102.22					
21 Apr 15	Blackstone Labs	61,382	Blackstone Labs Oil Analysis Report - Filed	\$0.00	\$25.00		\$0.00	\$25.00		\$0.00	\$25.00					
9 May 15	Discount Tire Co.	62,747	Nitto Motivo x 4, 275/40R20; Full Warranty; Road Force Balance	\$848.00	\$64.00		\$152.32	\$1064.32		\$66.42	\$1130.74					
9 May 15	Self		R&R Fuel Filter; Replace NEW Fuel Filter Seal; R&R Fuel Pressure Regulator; Replace NEW Fuel Pressure Regulator Seal	\$256.55	\$0.00		\$5.99	\$262.54		\$0.00	\$262.54					
26 Oct 15	Self	69,224	Cayenne Complete Oil Service Performed: Replaced 2x Aluminum Washer (900-123-106-30); Replaced 2x Oil Drain Plug (900-219-020-31); Replaced 1x Oil MAHLE OIM Filter Kit (996-107-25-53); Replaced 9 qts Mobil 1 0w-40	\$104.45	\$0.00		\$0.00	\$104.45		\$3.57	\$108.02					
	Blackstone Labs		Blackstone Labs Oil Analysis Report - Filed	\$0.00	\$28.00		\$0.00	\$28.00		\$0.00	\$28.00					
28 Dec 15	Self	72,200	Complete Brake System RY2, Brake pad Ubricant (05851), Replaced AF rom Brake pad a daliper bot (N-906-854-93), Replaced X From Brake Rotor (055-531-401-15), Replaced X From Brake Rotor (055-531-402-51), Replaced X From Brake Rotor (055-531-402-51), Replaced X From Brake Pad (055-531-402-51), Replaced X From Brake Pad Sensor (055-612-856-01), Replaced X From Brake Pad Sensor (055-612-856-01), Replaced X From Brake Pad Sensor (055-612-856-01), Replaced X From Brake Pad Sensor (055-612-905-01), Replaced X From Brake Pad Sensor (055-612-905-01), Replaced X From Brake Pad Sensor (195-612-905-901), Replaced X From Brake Pad Sensor (195-612-905-900-901), Pad Sensor (195-612-905-900-901), Pad Sensor (195-612-905-900-901), Pad Sensor (195-612-905-900-901), Pad Sensor (195-612-900-901), Pad Sensor (195-	\$565.50	\$0.00	\$31.40	\$0.00	\$596.90		\$0.00	\$596.90					
28 Dec 15			R^2 Driving Light Bulbs	\$33.22	\$0.00	\$0.00	\$0.00	\$33.22		\$0.00	\$33.22					
28 Dec 15			Complete Brake System Flush	\$0.00	\$0.00	\$82.02	\$0.00	\$82.02		\$0.00	\$82.02					
5 Feb 17		90,173	Cayenne Complete Oil Service Performed: Replaced 2x Aluminum Washer (900-123-106-30); Replaced 1x Oil MAHLE OilM Filter Kit (996-107-225-53); Replaced 9 (194 Mobil 1 0w-40 Replaced 2x Engine Air Filter (955-110-131-10)					\$0.00			\$0.00					
	Blackstone Labs		Blackstone Labs Oil Analysis Report - Filed	\$0.00	\$28.00		\$0.00	\$28.00			\$28.00					
15 Mar 17	Self	90,300	R2 Starter, R2 Water Pump, gasket; R2 thermostat, thermostat housing gasket, R2 coolant Porsche pink; R2 vent line to airfoil separator; R2 upper and lower radiator hoses; R2 coolant expansion tank and expansion tank on; R2 water temps pending unit; R2 three water hoses to coolant pipes at firewall side; R2 let and right reference sending units (under coolant pipes); R2 8x spark plugs; Checked all 8 coil packs, no issues;	\$891.96	\$0.00	\$0.00	\$0.00	\$891.96			\$891.96					