

Cedar Cross Service

775 Cedar Cross Road

Dubuque, IA 52001

Phone Number: (563) 589-9136

Fax Number:

Customer: Jeff Spahn	Date: 1/19/2010 8:34 AM
Company:	VIN: WPOJB2927LS860257
License NO: 942 XEP	Technician: Brian
Odometer: 102875	Order NO: 41936

VEHICLE ALIGNMENT REPORT

PORSCHE, 1990, 928

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	5.06°	3.00°	4.00°	4.62°
		Right	4.82°	3.00°	4.00°	4.92°
	Camber	Left	-0.79°	-0.66°	-0.34°	-0.43°
		Right	-0.56°	-0.66°	-0.34°	-0.46°
	Toe	Left	-0.09°	0.08°	0.17°	0.13°
		Right	0.25°	0.08°	0.17°	0.13°
Total		0.16°	0.16°	0.34°	0.26°	
Rear	Camber	Left	-1.21°	-0.81°	-0.50°	-0.73°
		Right	-1.24°	-0.81°	-0.50°	-0.69°
	Toe	Left	0.23°	0.08°	0.23°	0.16°
		Right	0.13°	0.08°	0.23°	0.15°
		Total	0.36°	0.16°	0.47°	0.31°
	Thrust Angle			0.05°	—	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		14.84°	—	—	14.58°
	Right		14.39°	—	—	14.19°
Included Angle	Left		14.05°	—	—	14.15°
	Right		13.83°	—	—	13.73°
Toe Out On Turns	Left		—	1.00°	1.00°	—
	Right		—	1.00°	1.00°	—
Max Turn Inside	Left		—	—	—	—
	Right		—	—	—	—
Toe Curve Change	Left		—	—	—	—
	Right		—	—	—	—
Setback	Front		0.03"	—	—	-0.01"
	Rear		-0.04"	—	—	-0.11"
Track Width Diff.			-0.48"			-0.50"
Wheel Base Diff.			0.07"			0.10"
Front Ride Height	Left		—	—	—	—
	Right		—	—	—	—
Rear Ride Height	Left		—	—	—	—
	Right		—	—	—	—
Frame Angle						—

GENERAL INFORMATION

1000 0000 0000 0000

1000 0000 0000 0000

1000 0000 0000 0000

1000 0000 0000 0000

NO.	DESCRIPTION	AMOUNT	DATE	REMARKS
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100