

Vehicle Model:	928	Safety Inspection Fee:	\$ 12.75
Vehicle Year/Type:	1986 / PASSENGER CAR	Safety Repair Costs:	\$ 0.00
Engine Size:	5000	Emission Test Fee:	\$ 27.00
Cylinders/Ignition:	8 / C	Emission Repair Costs:	\$ 0.00
Transmission/GVW:	MANUAL / 4123		
Color/Engine/Fuel Type:	154635 / GASOLINE	Total Inspection Cost:	\$ 39.75

Emissions Test Results

Pollutant	High Speed Emission Results			Low Speed Emission Results		
	RPM: 2725			RPM: 747		
	Standard	Current Reading	Result	Standard	Current Reading	Result
HC (ppm):	220	48	PASS	220	148	PASS
CO (ppm):	1.20	0.56	PASS	1.20	0.48	PASS
CO2 (%) :		13.6			13.6	
NO2 (ppm):		1.2			1.3	
NOX (ppm):	>6.0	14.16	PASS	>6.0	14.04	PASS


Gas Cap Missing: No Gas Cap Testable: Yes Gas Cap Integrity: PASS Safety Items: PASS

OVERALL RESULT: PASS

Certificate Number Issued: M03305029

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your annual safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedures manuals.



Certified Inspector's Signature

VIN: WP0JB0927GS862925



Plate Type: 1, Plate Number: BB6W924, TxDot:

