

# Pre-Purchase/ Used Vehicle Inspection

## A. VEHICLE DATA

Vehicle identification number: WP0AA2990TS321849

Odometer reading: 117908 miles

Model/type: 993330 Carrera

Repair order number: 28250

Date of first registration: 17 December 1996

Date: 6 September 2016

## B. VEHICLE DOCUMENTATION

- |  |  |
|--|--|
| <input checked="" type="checkbox"/> No uncompleted service campaigns   | <input checked="" type="checkbox"/> Warranty & maintenance booklet |
| <input checked="" type="checkbox"/> Fault memory/vehicle analysis report   | <input checked="" type="checkbox"/> Owner's manual                 |
| <input checked="" type="checkbox"/> Vehicle tool kit, <u>jack</u> , <u>compressor</u> , emergency tire kit, spare wheel, wheel anti-theft protection # ___ |  |

Comments: Check Engine Light On, Faults For Secondary Air. Jack & Compressor Are Missing. No Manual In Vehicle.

## C. VEHICLE EXTERIOR (FUNCTION AND CONDITION)

- |  |   |
|--|---|
| <input checked="" type="checkbox"/> Body/convertible top | <input checked="" type="checkbox"/> Front exterior lights           |
| <input checked="" type="checkbox"/> Paintwork            | <input checked="" type="checkbox"/> Rear exterior lights            |
| <input checked="" type="checkbox"/> Doors/lids           | <input checked="" type="checkbox"/> Headlights and additional lamps |
| <input checked="" type="checkbox"/> Underbody            | <input checked="" type="checkbox"/> Headlight adjustment            |
| <input checked="" type="checkbox"/> Wheels               | <input checked="" type="checkbox"/> Spoiler                         |

Comments: Minor Scratches On Paint. Engine Belly Pan Is Missing. Minor Scrapes On Wheels. Fog Lamp Lenses Are Cracked Spoiler Is Noisy When Operating. Minor Rock Chips On Headlamp Lenses.

## D. WHEELS/TIRES

- |   |                            |
|---|----------------------------|
| <input checked="" type="checkbox"/> Tread depth (min. 2 mm)   | Front left: <u>4.5</u> mm  |
| <input checked="" type="checkbox"/> Tire approval   | Rear left: <u>4.0</u> mm   |
| <input checked="" type="checkbox"/> Tire sizes correct  | Rear right: <u>5.0</u> mm  |
| <input checked="" type="checkbox"/> Tire pressures, psi FL <u>36</u> FR <u>36</u> RL <u>36</u> RR <u>36</u> | Front right: <u>4.5</u> mm |
| <input type="checkbox"/> Tire pressure monitor batteries  | Spare wheel: _____ mm      |
| Remaining months FL _____ FR _____ RL _____ RR _____  |                            |

Comments: Front Tires Worn On Inside Edges, Minor Feathering On Insides Of Rear Tires

## E. DRIVE SYSTEM/UNDERBODY

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Exhaust system                                      | <input checked="" type="checkbox"/> Wheel bearings                          |
| <input checked="" type="checkbox"/> Chassis/wheel suspension (shock absorbers, springs) | <input checked="" type="checkbox"/> Brake lines/hoses                       |
| <input type="checkbox"/> Air suspension   | <input checked="" type="checkbox"/> Brake pads: F <u>7</u> mm R <u>6</u> mm |
| <input checked="" type="checkbox"/> Anti-roll bar bearings                              | <input checked="" type="checkbox"/> Brake discs                             |
| <input checked="" type="checkbox"/> Axle joint  | <input checked="" type="checkbox"/> Brake calipers, air ducts, covers       |
| <input checked="" type="checkbox"/> Driven axles  | <input checked="" type="checkbox"/> Fuel system                             |
| <input type="checkbox"/> Transfer case  | <input type="checkbox"/> Radiator/fan                                       |
| <input checked="" type="checkbox"/> Steering gear                                       | <input type="checkbox"/> Radiator hoses/connections (leaks)                 |

Comments: Right Muffler Is Missing. Front Right Suspension Previously Replaced. Outer C/V Boots Split, C/V Joints Are Dry.

Wetness From Steering Gear, Steering Is Heavy When Turning

# Pre-Purchase/ Used Vehicle Inspection

## F. ENGINE COMPARTMENT

- Ignition system
- Alternator/on-board voltage
- A/C compressor
- Belts (alternator/air-conditioning/fan/power steering)
- Engine (no visible defects, fluid loss, leaks)
- Electrical connections and fuses
- Battery: State of charge/voltage State of health  
%80 SOC, 12.34V

## G. FLUIDS (FILL LEVELS/LEAKS)

- Battery
- Engine oil
- Brake fluid/clutch fluid
- Front/rear axle differential oil
- Transmission oil
- Coolant (antifreeze protection: - \_\_\_\_\_°C)
- Power steering hydraulic oil
- Windscreen/headlight washer fluid

Comments: Ignition Cables Are Cracking. A/C Compressor Not Switching On, Possible Low Charge.

Maintenance History Is Unknown, Possibly Due For Fluid Changes.

## H. INTERIOR (FUNCTION AND CONDITION)

- |  |   |
|--|---|
| <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Door locking system (child-proof locks)</li> <li><input checked="" type="checkbox"/> Remote control</li> <li><input checked="" type="checkbox"/> Alarm system and immobiliser</li> <li><input checked="" type="checkbox"/> Ignition/ignition lock</li> <li><input checked="" type="checkbox"/> Steering wheel lock</li> <li><input checked="" type="checkbox"/> Horn</li> <li><input checked="" type="checkbox"/> Airbag system (child seat deactivation)</li> <li><input checked="" type="checkbox"/> Wipers front/rear</li> <li><input checked="" type="checkbox"/> Headlight, windscreen &amp; rear washer system</li> <li><input checked="" type="checkbox"/> Steering column adjustment</li> <li><input checked="" type="checkbox"/> Seat belts and seat belt height adjustment</li> <li><input checked="" type="checkbox"/> Seat adjustment/position memory/heating</li> <li><input checked="" type="checkbox"/> Glove box</li> <li><input type="checkbox"/> Cup holders</li> </ul> | <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Ashtrays</li> <li><input checked="" type="checkbox"/> Cigarette lighter/sockets (12V)</li> <li><input checked="" type="checkbox"/> Instrument panel</li> <li><input checked="" type="checkbox"/> Warning lights and horns</li> <li><input checked="" type="checkbox"/> On-board clock</li> <li><input type="checkbox"/> On-board computer</li> <li><input type="checkbox"/> PCM (radio, phone, CD, nav)</li> <li><input checked="" type="checkbox"/> Interior lighting</li> <li><input checked="" type="checkbox"/> Heating/ventilation/air-conditioning</li> <li><input checked="" type="checkbox"/> Side/rear-view mirror adjustment</li> <li><input checked="" type="checkbox"/> Power windows</li> <li><input checked="" type="checkbox"/> Hood/tailgate release</li> <li><input checked="" type="checkbox"/> Roof (Cabriolet, Targa, sunroof)</li> <li><input type="checkbox"/> Other: _____</li> </ul> |
|--|---|

Comments: Cigarette Light Did Not Function

## I. TEST DRIVE

- |  |   |
|--|---|
| <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Warm/Cold start/idling characteristics</li> <li><input checked="" type="checkbox"/> Braking effect (service brake and handbrake)</li> <li><input checked="" type="checkbox"/> Electronic Stability System (PSM, etc.)</li> <li><input checked="" type="checkbox"/> ABS</li> <li><input checked="" type="checkbox"/> Suspension system</li> <li><input type="checkbox"/> PASM/air suspension</li> <li><input checked="" type="checkbox"/> Power steering/Servotronic</li> <li><input checked="" type="checkbox"/> Steering wheel centred</li> <li><input checked="" type="checkbox"/> Straight-ahead travel</li> </ul> | <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Clutch play</li> <li><input checked="" type="checkbox"/> Gear change</li> <li><input checked="" type="checkbox"/> Road behaviour/handling</li> <li><input checked="" type="checkbox"/> Vehicle performance</li> <li><input checked="" type="checkbox"/> Heating/ventilation, air-conditioning</li> <li><input type="checkbox"/> ParkAssist/reversing camera</li> <li><input type="checkbox"/> Cruise control (all functions)</li> <li><input type="checkbox"/> PCM function</li> <li><input checked="" type="checkbox"/> No unusual noises/vibrations</li> </ul> |
|--|---|

Comments: Steering Wheel Is Off-Centered. Steering Effort Is High. Clutch Engagement Is High When Releasing Pedal

Inspection technician signature:

