

Notes:


RavenWorks LLC
Reconditioned Fuel Injectors
 10900 89th Avenue North
 Maple Grove, MN 55369
 763-463-3452

Before Cleaning:	GREY
After Cleaning:	WHITE

FUEL INJECTOR DATA SHEET

Test Performed	1	2	3	4	5	6	7	8		
Leak Test (Pass/Fail)	pass	pass	pass	pass	pass	pass				
	pass	pass	pass	pass	pass	pass				
Spray Patterns (Good,Fair,Bad)	good	good	good	good	good	good				
	good	good	good	good	good	good				
Static Flow (cc's) 20.0 seconds wide open	92	92	92	92	91	93				
	92	92	92	92	92	92				
Pulsed Flow (cc's) 40.0 seconds 2400RPM 6.0Ms	45	45	45	45	45	45				
	45	45	45	45	45	45				
cc/minute-PSI@43.5psi	276	276	276	276	276	276				
lbs per hour	26.3	26.3	26.3	26.3	26.3	26.3				
Injector Balance% (before and after diff.)			Before%:	2.2%						
			After%:	<1%						

Notes: Injectors were in good shape before cleaning. Improved slightly after cleaning. No leaking, parts replaced.