

HERGESHEIMER

MAINTENANCE & SAFETY INSPECTION

NAME _____

MILEAGE 32378 DATE 8-23-11


VEHICLE 996 TT

INSPECTED BY Eric Johnson

	GOOD	FAIR	NEEDS SERVICE		GOOD	FAIR	NEEDS SERVICE
INSIDE VEHICLE				OUTSIDE VEHICLE			
STEERING PLAY	X	—	—	HEADLIGHTS	—	—	—
BRAKE PEDAL	X	—	—	- HIGH BEAM	X	—	—
EMERGENCY BRAKE	X	—	—	- LOW BEAM	X	—	—
HORN	X	—	—	TAIL LIGHTS	X	—	—
WINDSHLD WIPERS	X	—	—	BRAKE LIGHTS	X	—	—
WINDSHLD WASHERS	X	—	—	FOG LIGHTS	X	—	—
MIRRORS	—	—	X Rt side wont adjust 10/05	TURN SIGNALS	X	—	—
DEFROSTER	—	—	—	SIDE MARKER LIGHTS	X	—	—
- FRONT	X	—	—	BACKUP LIGHTS	X	—	—
- REAR	X	—	—	LICENSE PLATE LIGHTS	X	—	—
SPARE TIRE / JACK	X	—	—	WIPER BLADES	X	—	—
AIR CONDITIONER	X	—	—	TIRE INFLATION	—	—	—
SHIFT LINKAGE	X	—	X short shift Cable falling off transmission	- FRONT	38 PSI	X	—
UNDERHOOD				- REAR	44 PSI	X	—
FUEL LINES & FITTINGS	X	—	—	TIRE CONDITION	—	—	X worn on edges
AIR FILTER	X	—	X Dirty	- FRONT	—	—	X Color on inside edge
V-BELTS	X	—	—	- REAR	—	—	X Color on inside edge
RADIATOR HOSES	X	—	—	ALIGNMENT	Set up for Race	X	—
HEATER HOSES	X	—	—	LATCHES	X	—	—
PCV VALVE & HOSE	X	—	—	FLUID LEVELS			
VACUUM HOSES	X	—	—	ENGINE OIL	—	—	X warning light
HOOD SUPPORTS	X	—	—	COOLANT	—	—	X low on!
SPARK PLUG WIRES	X	—	—	BRAKE FLUID	—	—	X Low AT2B62
BATTERY TERMINALS	X	—	—	AT2 TRANSMISSION FLUID	X	—	—
THROTTLE LINKAGE	X	—	—	CLUTCH	X	—	—
WHEEL BEARINGS	X	—	—	POWER STEERING FLUID	—	—	X low
UNDERNEATH				WASHER FLUID	X	—	—
SHOCKS & STRUTS	X	—	—	BATTERY FLUID	X	—	—
TIE ROD ENDS	X	—	—	FLUID LEAKS			
BALL JOINTS	X	—	—	ENGINE OIL (see other side)	X	—	—
STEERING LINKAGE	X	—	—	COOLING SYSTEM	—	X	Stain around up area -
BRAKE HOSES	X	—	—	BRAKES / BRAKE LINES	X	—	—
EXHAUST SYS / MUFFLER	X	—	—	TRANSMISSION & HOSES	X	—	—
EMERG. BRAKE CABLES	X	—	—	DIFFERENTIAL	X	—	—
CV-JOINTS/AXLE BOOTS	X	—	—	POWER STEERING & HOSES	X	—	—
DIFFERENTIAL LUBE	X	—	—	FUEL TANK & LINES	X	—	—
BRAKE INSPECTION	X	10% 2-70%	X need fluid BRAKES				
IMPACT DAMAGE	X	—	—				
WIRING	X	—	—				

NOTES:

- ENGINE FLUID LEAKS**
 OIL RETURN TUBES
 OIL PRESSURE SWITCH
 OIL SUCTION HOSE
 OIL THERMO STAT
 CHAIN COVER
 - LEFT
 - RIGHT
 CAM SEAL
 - LEFT
 - RIGHT
 FLYWHEEL SEAL
 OIL COOLER
 VALVE CVR GASKETS
 - LEFT
 - RIGHT
 OIL LINE
 ROCKER SHAFTS
 #8 MAIN CAP
 PULLY SEAL
 CAM BOXES



Clutch Pedal goes hard ~~to the point where it's impossible to push~~ w/ key, off
 Pass mirror w/ out adjust in/out
 small scratch Rt door pocket cover
 New Transmission
 PS 9/10 shocks - Rt Front shock to sway bar link Bent
 window tint / sheet shift (noted shift cable falling off transmission)
 will need clutch soon
 Engine Belt ~~is~~ Gauded loose
 scratches on front brake caliper (small)
 scratches in driver door jam by latch (seat belt)
 Normal seat wear / ~~a~~ few scratches on ~~the~~ door panels
 AS mounted rear wing

COMPRESSION #1 _____ #2 _____ #3 _____ #4 _____ #5 _____ #6 _____

OVERALL CONDITION OF INTERIOR (RATE 1-5, 5 BEING EXCELLENT) 4.5 nice
 COMMENTS _____

OVERALL CONDITION OF EXTERIOR (RATE 1-5, 5 BEING EXCELLENT) 3.8
 COMMENTS Scratches, Rock Damage.

03 946 TT

MM88 3.0 - 4.15 Lt Side
2000t
PNE Block

