



MORRIS BROTHERS

Morris Brothers Motorsports  
6528 S State St  
Murray, UT 84107  
385-474-6383

## Modern Porsche Courtesy



Bmw Of Murray  
**2009 Porsche 911**

VIN: WP0AB29969S722666  
Odo: 53,780 miles  
RO#: 000007202 10/19/2023



**Nick W.**  
Technician



**Chad**  
Service Advisor

Morris Brothers

🏠 6528 State Street  
Murray, UT, 84109

☎️ [385-474-6383](tel:385-474-6383)

<https://morrisbrosmotors.com/>

43 Good

[Open for details](#)

Road Test

Exterior Visual Video

NOTES

Windshield has rockchips.




10/19/23



10/19/23



10/19/23



10/19/23



10/19/23

## Engine cranking

### NOTES

Engine cranking is normal.



## HVAC Function

### NOTES


HVAC works as intended.



## Engine Performance

### NOTES

Over rev report.



10/19/23

## Under Deck Lid

### Battery

#### NOTES

Battery tested good.



10/19/23

### Air Filter

#### NOTES

Engine air filter is good.



10/19/23




10/19/23

### Drive Belts

#### NOTES

drive belts look good, no sign of excessive wear or damage.



10/19/23

## Brake Fluid

### NOTES

Brake fluid looks good.



10/19/23

## Under Car

### Engine and Trans Mounts

#### NOTES

Mounts look good, No sagging or cracking.



10/19/23



10/19/23

## Tires

### CONDITION

7/32 Tread Left





10/19/23




10/19/23


## Brakes

### CONDITION

8 mm



10/19/23



10/19/23

## Brake Lines and Hoses

### NOTES

Brake hoses and lines look good.



10/19/23



10/19/23



10/19/23



10/19/23

## Shocks and Struts

### NOTES

Struts look good, not leaking.



10/19/23



10/19/23



10/19/23



10/19/23

## Drive Axle Boots

### NOTES

Axle boots show no tears or cracks.



10/19/23



10/19/23

## Exhaust System

### NOTES

Has an aftermarket exhaust from cats back.



10/19/23

## Road Test

### Interior Visual



10/19/23

### Horn



### Warning Lights



10/19/23

### Lighting



10/19/23



10/19/23

### Stereo



### Wipers and washers



## Under Deck Lid

### Deck Lid/Frunk Struts Hoses and Rubber



10/19/23



10/19/23



10/19/23

## Under Car

### Oil Leak




10/19/23

### Chassis Integrity



10/19/23

### A/C Lines and Condenser



10/19/23

### Suspension/Sway Bar Bushings and End Links



10/19/23



10/19/23

## Road Test

Clutch feel

Steering

Braking

Chassis

## Under Deck Lid

Cabin Air Filter

Washer Fluid

Coolant Level

Cooling Fans

Transmission Fluid

## Under Car

Transmission leak

Fuel Leaks

## Clutch Hydraulics

## Cooling System

More Detail if Needed

Misc

Factory Service Schedule

Alignment

## 4 Needs future Attention

Under Deck Lid

### Engine Oil

NOTES

Vehicle has oil pressure warning.

### Power Steering Fluid

NOTES

Power steering has electric conversion. Power steering doesn't work all the time. The factory power steering lines are still on the vehicle.



10/19/23




10/19/23

Under Car

### Bump Stops/Tophats

NOTES

Bump stops are showing age, but are good to watch.




10/19/23



10/19/23



10/19/23



10/19/23

## Rack, Tie Rods and Ball Joints

### NOTES

Front suspension clicking when turning, vehicle has power steering conversion, looks to be related. Steering wheel vibrates when turning while stationary.



10/19/23



10/19/23





Oil Leak



Engine and Trans Mounts



Engine and Trans Mounts



Deck Lid/Frunk Struts





Battery



Air Filter



Air Filter



Exterior Visual Video





Exterior Visual Video



Exterior Visual Video



Exterior Visual Video



Exterior Visual Video






Interior Visual



Tires




Tires



Drive Belts





Brakes



Brakes



Brake Lines and Hoses



Brake Lines and Hoses





Brake Lines and Hoses



Brake Lines and Hoses



Warning Lights




Shocks and Struts






Shocks and Struts



Shocks and Struts



Shocks and Struts




Lighting





Lighting



Hoses and Rubber



Hoses and Rubber



Bump Stops/Tophats





Bump Stops/Tophats



Bump Stops/Tophats



Bump Stops/Tophats



Rack, Tie Rods and Ball Joints





Rack, Tie Rods and Ball Joints



Drive Axle Boots



Drive Axle Boots



Power Steering Fluid






Power Steering Fluid



Brake Fluid



Exhaust System



Engine Performance





Chassis Integrity



A/C Lines and Condenser



Suspension/Sway Bar Bushings and End Links



Suspension/Sway Bar Bushings and End Links