





BARNABA AUTOSPORT

Tag# PEARCE

Mileage 37,235

License Plate MAKTSNL

W	P	O	A	C	2	9	9	4	7	5	7	9	2	8	3	8
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---



I hereby acknowledge the damage noted above to be pre-existing on my vehicle.

I also acknowledge that if my vehicle condition is marked dirty that not all pre-existing damage may be visible.

X _____

Date X _____

The 2020 Volvo XC90 Is Amazing

People looking for an award winning suv are using these top searches.

Luxury Auto

2007 Porsche 911 GT3

PDF Window Sticker

[Get your PDF and Image Window Sticker](#) ↗

Advanced VIN Decoding Available

[Get your AVD PDF](#) ↗

Vehicle History Report

[Get your detailed vehicle history report](#) ↗

Division: PCNA
Commission #: 635530

Prod Month: 2007-04-01
VIN: **WP0AC29947S792838**
Price: \$111,535.00
Exterior: GT Silver Metallic
Interior: Black Leather Seats
Warranty Start: May 23, 2007

BASE Porsche Base Model
28 Black Leather Seats
342 Heated Front Seats

490	Sound Package Plus
810	Floor Mats - Interior Color
U2	GT Silver Metallic
XSC	Porsche Crest in Headrest

The Volvo XC90 Will Turn Heads

Discover everything the 2020 Volvo XC90 has to offer with top searches

Luxury Auto

PDF Window Sticker

[Get your PDF and Image Window Sticker](#)

Advanced VIN Decoding Available

[Get your AVD PDF](#)

Vehicle History Report

[Get your detailed vehicle history report](#)

All-Inclusive Overwater Resort

Explore offers on overwater resorts with all-inclusive options using top searches

Luxury Life

VIN Analytics

[Window Stickers](#) [About](#) [Contact Us](#) [Signup](#) [Login](#)

[Terms of Service](#) [Privacy Policy](#) [Cookie Policy](#) [Disclaimer](#)

© 2021 VIN Analytics, LLC. All rights reserved.



This report provided free of charge by:

Barnaba Autosport
1183 Pierson Dr Ste 102, Batavia, IL 60510
(630) 406-1700

★ 5.0 out of 5.0
15 Verified Reviews



Vehicle History Report™

US \$39.99

2007 PORSCHE 911 GT3

VIN: WP0AC29947S792838
COUPE
3.6L H6 F DOHC
GASOLINE
REAR WHEEL DRIVE



Moderate damage



7 Previous owners



11 Service history records



Types of owners: Personal lease, Personal



37,000 Last reported odometer reading



This CARFAX Report Provided by:

Barnaba Autosport

★ 5.0 / 5.0 15 Verified Reviews

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 8/2/21 at 4:18:40 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

	Owners 1-5	Owner 6	Owner 7
Year purchased	2007	2013	2015
Type of owner	See Details	Personal	Personal
Estimated length of ownership	5 yrs. 9 mo.	1 yr. 8 mo.	6 yrs. 3 mo.
Owned in the following states/provinces	See Details	California, Illinois	Illinois
Estimated miles driven per year	See Details	4,805/yr	1,784/yr
Last reported odometer reading	17,940	26,088	37,000



Title History


CARFAX guarantees the information in this section

	Owners 1-5	Owner 6	Owner 7
Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem	✓ Guaranteed No Problem	✓ Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem	✓ Guaranteed No Problem	✓ Guaranteed No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.
[Register](#) | [View Terms](#) | [View Certificate](#)

CARFAX Additional History	Owners 1-5	Owner 6	Owner 7
Not all accidents / issues are reported to CARFAX			
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage Damage reported: 07/31/2012 and 08/30/2018.	Damage Reported	No New Issues Reported	Damage Reported
Manufacturer Recall Check with an authorized Porsche dealer for any open recalls.	✓ No Recalls Reported	✓ No Recalls Reported	✓ No Recalls Reported
Basic Warranty <u>Original warranty</u> estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Detailed History																								
<p>Owner 1 Personal Lease Vehicle</p> <p>Purchased: 2007</p> <table border="1"> <thead> <tr> <th>Date</th> <th>Mileage</th> <th>Source</th> <th>Comments</th> </tr> </thead> <tbody> <tr> <td>05/23/2007</td> <td>3</td> <td>Higginbotham Automobiles LLC Jackson, MS 601-984-3700 mercedesporsche.com ★ 4.5 / 5.0 176 Verified Reviews ✓ ❤ 3,768 Customer Favorites</td> <td>Vehicle sold</td> </tr> <tr> <td>06/18/2007</td> <td></td> <td>West Virginia Motor Vehicle Dept. Oshkosh, WI Title #CB06128</td> <td>Title issued or updated - First owner reported - Titled or registered as personal lease vehicle - Loan or lien reported</td> </tr> <tr> <td>09/07/2007</td> <td></td> <td>Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com</td> <td>✂ Vehicle serviced - Tire(s) balanced - Tire(s) mounted</td> </tr> <tr> <td>09/19/2007</td> <td>5,639</td> <td>Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com</td> <td>Vehicle sold</td> </tr> <tr> <td>09/27/2007</td> <td></td> <td>Ohio Motor Vehicle Dept. Willoughby, OH Title #4301738670</td> <td>Title issued or updated - Dealer took title of this vehicle while it was in inventory</td> </tr> </tbody> </table> <div style="text-align: center; margin-top: 10px;">  <div style="border: 1px solid gray; padding: 5px; display: inline-block;"> Two states? Vehicle leasing companies often title a car in one state but register it to be driven in another. </div> </div>	Date	Mileage	Source	Comments	05/23/2007	3	Higginbotham Automobiles LLC Jackson, MS 601-984-3700 mercedesporsche.com ★ 4.5 / 5.0 176 Verified Reviews ✓ ❤ 3,768 Customer Favorites	Vehicle sold	06/18/2007		West Virginia Motor Vehicle Dept. Oshkosh, WI Title #CB06128	Title issued or updated - First owner reported - Titled or registered as personal lease vehicle - Loan or lien reported	09/07/2007		Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com	✂ Vehicle serviced - Tire(s) balanced - Tire(s) mounted	09/19/2007	5,639	Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com	Vehicle sold	09/27/2007		Ohio Motor Vehicle Dept. Willoughby, OH Title #4301738670	Title issued or updated - Dealer took title of this vehicle while it was in inventory
Date	Mileage	Source	Comments																					
05/23/2007	3	Higginbotham Automobiles LLC Jackson, MS 601-984-3700 mercedesporsche.com ★ 4.5 / 5.0 176 Verified Reviews ✓ ❤ 3,768 Customer Favorites	Vehicle sold																					
06/18/2007		West Virginia Motor Vehicle Dept. Oshkosh, WI Title #CB06128	Title issued or updated - First owner reported - Titled or registered as personal lease vehicle - Loan or lien reported																					
09/07/2007		Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com	✂ Vehicle serviced - Tire(s) balanced - Tire(s) mounted																					
09/19/2007	5,639	Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com	Vehicle sold																					
09/27/2007		Ohio Motor Vehicle Dept. Willoughby, OH Title #4301738670	Title issued or updated - Dealer took title of this vehicle while it was in inventory																					
<p>Owner 2 Personal Vehicle</p> <p>Purchased: 2007</p>																								

Date	Mileage	Source	Comments
10/12/2007		Ohio Motor Vehicle Dept. Boca Raton, FL Title #4301744946	Title issued or updated - New owner reported
10/31/2007		Stoddard Imported Cars, Inc. Willoughby, OH 440-951-1040 stoddard.com	 Vehicle serviced - Pre-delivery inspection completed

Owner 3
Purchased: 2008

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
989 mi/yr



Date	Mileage	Source	Comments
06/26/2008	7,549	California Motor Vehicle Dept. Encino, CA	Odometer reading reported
07/03/2008	7,556	California Inspection Station	Passed emissions inspection
07/08/2008		California Motor Vehicle Dept. Encino, CA	Title issued or updated - New owner reported - Loan or lien reported
07/10/2008		The Auto Gallery Woodland Hills, CA 818-884-4411 theautogallery.com ★ 4.9 / 5.0 30 Verified Reviews ✓	 Vehicle serviced - Maintenance inspection completed
07/21/2008		California Motor Vehicle Dept. Encino, CA	Title issued or updated - Correction to record - Loan or lien reported
05/22/2009		The Auto Gallery Woodland Hills, CA 818-884-4411 theautogallery.com ★ 4.9 / 5.0 30 Verified Reviews ✓	 Vehicle serviced - Maintenance inspection completed
05/19/2011	10,629	The Auto Gallery Woodland Hills, CA 818-884-4411 theautogallery.com ★ 4.9 / 5.0 30 Verified Reviews ✓	 Vehicle serviced - Maintenance inspection completed - Engine oil/fluid leak checked - Brakes checked - Fluids checked - Oil and filter changed - Tire condition and pressure checked
07/27/2011		California Motor Vehicle Dept. Encino, CA	Title issued or updated - Loan or lien released
08/09/2011	10,637	The Auto Gallery Woodland Hills, CA 818-884-4411 laautogallery.com ★ 4.9 / 5.0 30 Verified Reviews ✓	Vehicle offered for sale

Owner 4
Purchased: 2011

Date	Mileage	Source	Comments

Personal Vehicle

09/27/2011	10,690	California Motor Vehicle Dept. Huntington Beach, CA	Odometer reading reported
11/20/2011	11,464	Dealer Inventory	Vehicle offered for sale
01/14/2012	11,477	California Inspection Station Upland, CA	Passed emissions inspection
01/20/2012		California Motor Vehicle Dept. Huntington Beach, CA	Title issued or updated - New owner reported - Loan or lien reported
03/05/2012		California Motor Vehicle Dept. Huntington Beach, CA	Title issued or updated - Loan or lien reported

Owner 5


Purchased: 2012



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle

6,075 mi/yr

Date	Mileage	Source	Comments
03/05/2012	11,493	California Motor Vehicle Dept. Riverside, CA	Odometer reading reported
03/06/2012	11,539	California Inspection Station Riverside, CA	Passed emissions inspection
03/19/2012		California Motor Vehicle Dept. Riverside, CA	Title issued or updated - New owner reported - Loan or lien reported
07/17/2012		California Motor Vehicle Dept. Riverside, CA	Registration updated when owner moved the vehicle to a new location
07/31/2012		Damage Report	 Damage reported: moderate damage - Damage to front - Damage to left front - Damage to left rear - Damage to right front This incident was first available for display by CARFAX on 12/02/2016.


CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION





Damage Severity Scale ⓘ



Damage Location



03/18/2013	17,785	Auto Auction	Listed as a dealer vehicle - Vehicle sold
			Millions of used vehicles are bought and sold at auction every year.
03/21/2013	17,896	California Inspection Station San Diego, CA	Passed emissions inspection
03/21/2013		Dealer Inventory	Vehicle offered for sale
03/25/2013	17,898	Dealer Inventory San Diego, CA	Vehicle offered for sale
04/22/2013		California Motor Vehicle Dept. Riverside, CA	Title issued or updated - Loan or lien reported
06/05/2013	17,940	Eurospec Porsche Service And Repair Escondido, CA 760-747-4010 ★ 5.0 / 5.0 36 Verified Reviews ✓	 Vehicle serviced - Pre-delivery inspection completed

Owner 6

Purchased: 2013



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
4,805 mi/yr

Date	Mileage	Source	Comments
06/07/2013	17,971	California Motor Vehicle Dept. Escondido, CA	Odometer reading reported

07/05/2013	18,096	Eurospec Porsche Service And Repair Escondido, CA 760-747-4010 ★ 5.0 / 5.0 36 Verified Reviews ✓	Vehicle serviced
07/24/2013		California Motor Vehicle Dept. Escondido, CA	Title issued or updated - New owner reported
11/26/2013		California Motor Vehicle Dept. Escondido, CA	Title issued or updated - Loan or lien reported
01/18/2014	20,929	Eurospec Porsche Service And Repair Escondido, CA 760-747-4010 ★ 5.0 / 5.0 36 Verified Reviews ✓	Vehicle serviced - Oil and filter changed
06/20/2014	23,200	Eurospec Porsche Service And Repair Escondido, CA 760-747-4010 ★ 5.0 / 5.0 36 Verified Reviews ✓	Vehicle serviced - Brake fluid flushed/changed - Oil and filter changed
02/13/2015	26,081	Dealer Inventory	Vehicle offered for sale
02/14/2015	26,088	California Inspection Station	Passed emissions inspection
02/24/2015		California Motor Vehicle Dept. Escondido, CA	Title issued or updated - Loan or lien reported
02/27/2015		Illinois Motor Vehicle Dept.	Vehicle purchase reported
03/26/2015		Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed

Owner 7

Purchased: 2015




Low mileage! This owner drove less than the industry average of 15,000 miles per year.


Personal Vehicle
1,784 mi/yr

Date	Mileage	Source	Comments
04/14/2015	26,138	Illinois Motor Vehicle Dept. Geneva, IL Title #151046071840	Title issued or updated - New owner reported - Loan or lien reported
05/18/2015		Eurospec Porsche Service And Repair Escondido, CA 760-747-4010 ★ 5.0 / 5.0 36 Verified Reviews ✓	Vehicle serviced
10/21/2015	32,222	Euroquipe Saint Charles, IL 630-377-3774 euroquipe.com ★ 5.0 / 5.0 16 Verified Reviews ✓ ❤️ 22 Customer Favorites	Vehicle serviced

07/09/2016	Illinois Inspection Station Naperville, IL	Passed emissions inspection
07/12/2016	Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed
01/20/2017	Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed
03/27/2018	Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed

08/30/2018 Damage Report  Damage reported
- Damage to front

**CARFAX HAS
THE MOST
ACCIDENT &
DAMAGE
INFORMATION**



Not all damage is caused by an accident. Get the car inspected before you buy. [Learn More](#)

03/29/2019	Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed - Correction to record
05/26/2020	Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed
05/14/2021 37,000	Illinois Inspection Station Naperville, IL	Passed emissions inspection
05/18/2021	Illinois Motor Vehicle Dept. Geneva, IL	Registration issued or renewed

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event

become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 8/2/21 at 4:18:40 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX.
- Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved.
8/2/21 4:18:40 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2007 PORSCHE 911 vehicle (VIN: WP0AC29947S792838), which is based on information supplied to CARFAX and available as of 8/2/21 at 5:18 PM (EDT).

Customer Signature

Date

Dealer Signature

Date



A. VEHICLE DATA

Name: Cordell Pearce
 VIN: WP0AC29947S792838
 Mileage: 37,235
 Engine Number: _____

Repair Order Number: 1812
 Year/Make/Model: 2007 Porsche 911 GT3
 Date: 08/02/2021
 Transmission Number: _____

B. LIGHTS, SWITCHES & ACCESSORIES—Pass or fail (Check one)

- | | |
|--|---|
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Ignition/Starter Switch | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Cigarette lighter |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Headlights—low beams/high beams | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Clock |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Emergency flasher switch | <input checked="" type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail Windshield and rear window wipers |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Fog/driving lights | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Windshield and rear window washer |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Stop lights | <input type="checkbox"/> Pass <input type="checkbox"/> Fail Headlight washers |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Key light | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Horn(s) |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Drive block system remote transmitter | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Warning display lights |
| <input type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail All exterior lights checked for operation | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Instrument panel dimming |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail All interior lights checked for operation | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Power window switches |

C. EXTERIOR: UNDERBODY, BODY, DOORS, LIDS & TOP—Pass or fail (Check one)

- Is there visible evidence of existing damage to the vehicle? Yes No
- | | |
|---|---|
| <input type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail Axle joints | <input checked="" type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail Underbody inspection |
| <input type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail Leaks: <u>engine</u> , transmission, differential, transfer case | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Exhaust system |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Gas cap | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Brake lines/hoses |
| <input type="checkbox"/> Pass <input type="checkbox"/> Fail Wheel locks | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Fuel lines/hoses |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Front/rear lid release actuation | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Glass—chips or cracks |
| <u>Door:</u> | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Brake calipers/cylinders air ducts |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Hinges | <input type="checkbox"/> Pass <input type="checkbox"/> Fail Trailer Hitch |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Door closing | Over revs detected? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Door locks | |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Check straps | |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Window lifter mechanisms | |
| <input type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail Seat adjusters | |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Sunroof/sliding roof mechanism and locks | Total operating hours <u>1076.50</u> |
| <input type="checkbox"/> Pass <input type="checkbox"/> Fail Cabriolet top operation | Vehicle has emissions ready status? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| <input type="checkbox"/> Pass <input type="checkbox"/> Fail Targa top operation | Fault Codes Detected? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

Range 1	Range 2	Range 3	Range 4	Range 5	Range 6
294	36	0	0	0	0

D. TIRES / BRAKES

- | |
|--|
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Tread depth (min. 4mm) |
| <input type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail Tire size: |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Tire pressures |
| <input type="checkbox"/> Pass <input type="checkbox"/> Fail Tire pressure monitor |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Brake pad wear |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail Approximate % of pad remaining |
| <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail l/f <u>50</u> % r/f <u>60</u> % l/r <u>70</u> % r/r <u>80</u> % |
| <u>5mm</u> <u>6mm</u> <u>8mm</u> <u>8mm</u> |

Measuring Points (in mm)	Inside	Center	Outside	TPMS Life
Front left	8	8	8	
Rear left	8	8	8	
Rear right	8	8	8	
Front right	8	8	8	
Spare wheel				

E. ENGINE COMPARTMENT—Pass or fail (Check one)

- | | | | | | |
|--|-------------------------------|-----------------------------|--|-------------------------------|--|
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Engine CO/HC | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Belts (alternator/air-conditioning/fan/p/s) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Alternator function | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Engine (no visible defects, fluid loss, leaks) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Ignition system | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Electrical connections and fuses |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Alternator/on-board voltage | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | OEM Battery <u>46</u> Voltage <u>12.6</u> |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | A/C compressor | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | PHEV High Voltage |

F. FLUIDS—Pass or fail (Check one)

- | | | | | | |
|--|-------------------------------|--|--|-------------------------------|------------------------------------|
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Engine oil | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Power steering hydraulic oil |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Front/rear axle differential oil | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Brake fluid/clutch fluid <u>0%</u> |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Transmission oil | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Windscreen/headlight washer fluid |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Coolant (antifreeze protection down to: <u>-46</u> °C) | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Diesel exhaust fluid (AdBlue) |

G. INTERIOR (function and condition) - Pass or fail (Check one)

- | | | | | | |
|--|--|--|--|--|---|
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Door locking system | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Cupholders |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Remote control | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Ashtrays |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Alarm system and immobilizer | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Cigarette lighter/sockets (12V) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Ignition/ignition lock | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Instrument panel (check while stationary) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Steering wheel lock | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | On-board clock |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Horn | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | On-board computer |
| <input checked="" type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Airbag system (child seat deactivation) | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | PCM (radio, telephone, CD, DVD, navi) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Wipers front/rear | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | CD changer |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Headlight and windscreen washer system | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Interior lighting |
| <input type="checkbox"/> Pass | <input type="checkbox"/> Fail | Steering column adjustment | <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Heating/ventilation/A/C/climate control) |
| <input type="checkbox"/> Pass | <input type="checkbox"/> Fail | Seat belts and seat belt height adjustment | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Exterior mirror/rear-view mirror adjust) |
| <input type="checkbox"/> Pass | <input type="checkbox"/> Fail | Seat adjustment/position memory/heating | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Power windows (anti-pinch protection) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Seat and head restraint upholstery | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Bonnet/tailgate release |
| <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Sun visors | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Roof (Cabriolet, Targa, sliding sunroof) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Roof lining | <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Cabriolet: wind deflector |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Floor mats and carpet | <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Equipment/Exclusive equipment: |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Interior trim and luggage compartment | | | |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Glove box | | | |

H. TEST DRIVE (minimum of 20 minutes) - Pass or fail (Check one)

- | | | | | | |
|--|--|--|--|--|--|
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | (Cold)-start/idling characteristics | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Gear change |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Braking effect (service brake and handbrake) | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Auxiliary heating |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | ABS | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Heating/ventilation system, a/c system |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Suspension system | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Rear window and mirror heating |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Electronic Stability System (PASM, etc.) | <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | ParkAssist/reversing camera |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Power steering/Servotronic | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | PCM (radio, telephone, CD, DVD, navi) |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Steering wheel centered | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Cruise control (all functions) |
| <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Straight-ahead travel | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Differential locks, all-wheel drive |
| <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Road behavior/handling | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Instrument panel (while vehicle in motion) |
| <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | Vehicle performance | <input type="checkbox"/> Pass | <input checked="" type="checkbox"/> Fail | No unusual noises/vibrations |
| | | | <input checked="" type="checkbox"/> Pass | <input type="checkbox"/> Fail | Warm-start/idling characteristics |

I. PAINT METER RESULTS

<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	Front Hood/Bonnet	(High) <u>N/A</u>	(Low) <u>N/A</u>	CLEAR FILM
<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	Passenger Front Fender	(High) <u>N/A</u>	(Low) <u>N/A</u>	CLEAR FILM
<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	Passenger Front Door	(High) <u>3.5</u>	(Low) <u>2.5</u>	
<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	Passenger Rear Door	(High) <u>N/A</u>	(Low) <u>N/A</u>	
<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	Passenger Rear Quarter	(High) <u>4.5</u>	(Low) <u>3.5</u>	
<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	Engine Compartment Lid/Hatch	(High) <u>N/A</u>	(Low) <u>N/A</u>	
<input type="checkbox"/> Pass	<input checked="" type="checkbox"/> Fail	Driver's Rear Quarter	(High) <u>16.5</u>	(Low) <u>7.0</u>	AREAS THAT ARE UNREADABLE
<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	Driver's Rear Door	(High) <u>N/A</u>	(Low) <u>N/A</u>	
<input type="checkbox"/> Pass	<input checked="" type="checkbox"/> Fail	Driver's Front Door	(High) <u>7.0</u>	(Low) <u>6.0</u>	
<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	Driver's Front Fender	(High) <u>N/A</u>	(Low) <u>N/A</u>	CLEAR FILM
<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	Roof	(High) <u>4.0</u>	(Low) <u>3.0</u>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Is there visible evidence of existing body damage to the vehicle?			
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	The body of the vehicle has structural damage and/or sub-par repair?			
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Panels are misaligned and have a wave like appearance?			
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<u>Panels have been painted</u> and there are signs of mismatched paint or inconsistencies in the finish of the paint?			
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Signs of structural damage, e.g. damaged flanges, loose or broken joining elements (spot welds, rivets, etc.) and/or deformities in the sheet metal?			
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Paint work is inconsistent in texture and color?			

J. COMMENTS

Has aftermarket high flow air filter. Has airbag light on due to aftermarket seats. Wiper blades worn/shredding. Right front shade is leaking. Has car rear main leak. Coils have started to crack. Has aftermarket sway bars and the rear bushings are cracked. Has GMC center muffler delete. Right rear CV boot has a hole in it. Right rear center lower control arm bushing is torn. Cabin filter is dirty. Has wheel studs on it. Has aftermarket air filter and housing and is also leak. Has roll bar and harness in it. Has the wrong battery (AGM). Has aftermarket wheels on it and are the wrong size. Has hood up for a cool suit. Upon test drive found that the clutch slips under hard acceleration, vehicle also pulls to the right. Has a rattle while driving. Passenger vanity lights in the visor are Tapped. Both center vents are broken. Driver side rear tail light has a red bulb out.

CERTIFICATION

The signatures of the technician and service director are confirmation that this Porsche has been meticulously inspected and that detected defects have been disclosed.

8/3/21 Brian Welfin
Date: Technician

08/03/2021 M. Mark
Date: Service Director



I have reviewed this inspection report and understand that it is given to show the condition of the vehicle at the time of its inspection and evaluation only, and is made without representation, guarantee or warranty of any kind, either expressed or implied or arising by operation of law. I acknowledge that no action has been taken to correct any condition reported, and that the safe operation and maintenance of the vehicle following the inspection is my sole responsibility.

Customer's Signature: _____

Date: _____

Barnaba Autosport
1183 Pierson Drive
Batavia, IL 60510