

leaks found at this time.

B PROSCHE MULTI-POINT INSPECTION

PMPI PROSCHE MULTI-POINT INSPECTION

47 DAMIANO, CHRISTOPHER LIC#: 27210902

ISP 0.30

(N/C)

49483 Perform Porsche multi-point inspection. Tire specs: front-8/32", rear-2/32". Brake pad specs: front & rear-12/32". Recommend: 1. Air bag lamp on. Coding needs to be changed for aftermarket seats. 2. RF inner door handle micro switch. Part placed on order. 3. Rear tires at minimum specification.

C** PORSCHE OIL SERVICE

PLOF PORSCHE OIL SERVICE

47 DAMIANO, CHRISTOPHER LIC#: 27210902

CP 1.00

101.00 101.00

1 996-107-225-53 OIL-FILTER INSERT 31.69 31.69 31.69

1 ZVW-239-003 ADDITIVE 4.68 4.68 4.68

1 ZVW-177-901 WINDOWWASH 4.48 4.48 4.48

9 Q-1-09-0101 MOBIL 1 0W40 7.48 7.48 67.32

49483 Perform Porsche oil service.

D** C/S - NEAR END OF WARR..... ADVISE OF ANYTHING NEEDED.

KM41 OK

47 DAMIANO, CHRISTOPHER LIC#: 27210902

CP 0.00

0.00 0.00

FOR YOUR ADDED CONVENIENCE THE SERVICE AND PARTS DEPARTMENT WILL BE OPEN AS FOLLOWS:

MONDAY THRU FRIDAY

7:30 A.M. - 6:00 P.M.

SATURDAY

8:00 A.M. - 2:00 P.M.

THANK YOU! PORSCHE

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	101.00
PARTS AMOUNT	108.17
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	209.17
LESS INSURANCE	0.00
SALES TAX	12.55
PLEASE PAY THIS AMOUNT	221.72