Work Log

Engine Module Bosch EDC17

Module Identification

Description	3.0TDIFSA
VIN	WP1AF2A21DLA39889
Hardware Number	7P0907401K
Part Number	7P5907401H

Current Fault Codes



i

7154

Warning Indicator On Test Not Completed This Monitoring Cycle Test Failed Since Last Clear Test Completed Since Last Clear Pending DTC Test Not Failed This Operation Cycle Fault Active

Short Test

Engine Module Bosch EDC17

Current Fault Codes

7154:

Warning Indicator On Test Not Completed This Monitoring Cycle Test Failed Since Last Clear Test Completed Since Last Clear Pending DTC Test Not Failed This Operation Cycle Fault Active

Tiptronic Transmission

No Faults Found

Porsche Stability Management / Anti-lock Brake System (ABS)

No Faults Found	V
Electronic Parking Brake	
No Faults Found	Ť
Tire Pressure Monitor	
No Faults Found	
Heating and Air Conditioning - HVAC	V
No Faults Found	
Airbag	V
No Faults Found	
Steering Wheel Electronics	V
No Faults Found	
CAN Gateway No Faults Found	V
Body Control Module Front No Faults Found	V
Body Control Module Rear	
No Faults Found	V

Door module front left No Faults Found	V
Door module front right	
No Faults Found	
Door module rear left	V
No Faults Found	
Door module rear right	V
No Faults Found	
Rear lid - Tailgate	V
No Faults Found	
Instrument cluster for 970, 958	V
No Faults Found	
Radio PCM 3.1 CDR31	V
No Faults Found	
Sports Chronometer	V
No Faults Found	
Park Assist	V
No Faults Found	

Backup Camera No Faults Found	v
Seat Electronics Driver	
No Faults Found	
Seat Electronics Passenger	V
No Faults Found	
Headlight Right No Faults Found	Ø
Headlight Left	
No Faults Found	\checkmark
Lane Change Assistant	•
No Faults Found	V
Trailer Module	
No Faults Found	•