



RAY CATENA PORSCHE

123 SOUTH MAIN STREET
EDISON, N.J. 08837
732-205-9010
www.raycatena.com



0401IPOCS69823

CELL: 732-707-5555

CUSTOMER NO. 31110	ADVISOR CONOR	94 TAG NO. 5008	INVOICE DATE 04/11/17	INVOICE NO. POCS69823
EURO PLUS 3713 ROUTE 1 NO. BRUNSWICK, NJ 08902 EUROPLUSNJ@GMAIL.COM	LABOR RATE 165.00	LICENSE NO.	MILEAGE 40,938	COLOR CARRARA WHI
	YEAR / MAKE / MODEL 11/PORSCHE/911 CARRERA GTS			DELIVERY DATE 09/29/11
	VEHICLE I.D. NO. WP0AB2A93BS721105			SELLING DEALER NO.
RESIDENCE PHONE	BUSINESS PHONE	F.T.E. NO.	P.O. NO.	R.O. DATE 04/11/17
COMMENTS				MO: 40939

LABOR & PARTS

J# 1 00POR0000 FLUIDS/PSI HOURS: 0.00 TECH(S):627 INTERNAL
 CHECK ALL FLUID LEVELS AND CHECK TIRE PSI
 TECH CHECKED AND TOPPED OFF ALL FLUID LEVELS AND CHECKED AND
 ADJUSTED ALL TIRE PSI
 COMPLETED

JOB # 1 TOTAL LABOR & PARTS 0.00

J# 2 93POZ PDI PORSCHE HOURS: 1.00 TECH(S):627 165.00
 CUST REQUEST PRE PURCHASE INSPECTION
 PPI COMPLETED

JOB # 2 TOTAL LABOR & PARTS 165.00

ESTIMATE
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$165.00 (+TAX)

COMMENTS
DROP

TOTALS

*****	TOTAL LABOR....	165.00
* METHOD OF PAYMENT *	TOTAL PARTS....	0.00
* []CASH []CHECK *	TOTAL SUBLET...	0.00
* []A/X []VISA *	TOTAL G.O.G....	0.00
* []MASTER *	TOTAL MISC CHG.	0.00
* []RCMC CHARGE *	TOTAL MISC DISC	0.00
*****	TOTAL TAX.....	11.35

THANK YOU

TOTAL INVOICE \$ 176.35

CUSTOMER SIGNATURE



PORSCHE

The Porsche Multi-Point Inspection Report

The Porsche Multi-Point Inspection Report is a series of thorough vehicle "health checks" performed by factory-trained Porsche technicians. It is designed to keep your Porsche operating in top condition and to minimize your chances of being inconvenienced on the road. If additional service is recommended on any listed item, your Porsche Service Advisor will be happy to speak with you about your options.

Customer Name _____ Year/Model _____ Engine Size _____

RO/Tag _____ Mileage _____ VIN _____ Date _____

Checked and Okay at this Time **May Require Future Attention** **Requires Immediate Attention**

Check Fluid Levels and Fill

OK FILL	OK FILL
<input checked="" type="checkbox"/> <input type="checkbox"/> Engine Oil	<input type="checkbox"/> <input type="checkbox"/> Brake Reservoir
<input type="checkbox"/> <input type="checkbox"/> Windshield Washer	<input type="checkbox"/> <input type="checkbox"/> Headlamp Washer
<input checked="" type="checkbox"/> <input type="checkbox"/> Power Steering	<input type="checkbox"/> <input type="checkbox"/> Coolant Recovery Reservoir
<input type="checkbox"/> <input type="checkbox"/> Transmission (if equipped w/ dipstick)	

Check Following Systems / Components

<input checked="" type="checkbox"/> <input type="checkbox"/>	Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
<input checked="" type="checkbox"/> <input type="checkbox"/>	Visually inspect headlamp alignment
<input checked="" type="checkbox"/> <input type="checkbox"/>	Windshield washer spray, wiper operation and wiper blades
<input checked="" type="checkbox"/> <input type="checkbox"/>	Windshield cracks and/or chips
<input checked="" type="checkbox"/> <input type="checkbox"/>	Heating, ventilation and air conditioning check
<input checked="" type="checkbox"/> <input type="checkbox"/>	Engine air cleaner filter
<input checked="" type="checkbox"/> <input type="checkbox"/>	Oil and/or fluid leaks
<input checked="" type="checkbox"/> <input type="checkbox"/>	Constant velocity (CV) drive axle boots (if equipped)
<input checked="" type="checkbox"/> <input type="checkbox"/>	Exhaust system (leaks, damage, loose parts)
<input checked="" type="checkbox"/> <input type="checkbox"/>	Steering and steering linkages
<input checked="" type="checkbox"/> <input type="checkbox"/>	Shocks/struts, air suspension and other suspension components for leaks and/or damage
<input checked="" type="checkbox"/> <input type="checkbox"/>	Brake system (including lines, hoses and parking brake)
<input checked="" type="checkbox"/> <input type="checkbox"/>	Engine cooling system, hoses and clamps
<input checked="" type="checkbox"/> <input type="checkbox"/>	Radiator, heater and air conditioning hoses for leaks / damage
<input checked="" type="checkbox"/> <input type="checkbox"/>	Accessory drive belt(s) Cracked
<input checked="" type="checkbox"/> <input type="checkbox"/>	Clutch operation (if equipped)
<input type="checkbox"/> <input type="checkbox"/>	State inspection due (if applicable) _____ / _____ / _____ Month Day Year
<input type="checkbox"/> <input type="checkbox"/>	Your last completed maintenance _____ Mileage ; _____ / _____ Month Year
<input type="checkbox"/> <input type="checkbox"/>	Your next factory scheduled maintenance is due at _____ Mileage ; _____ / _____ Month Year

Comments: **Over speed**
Range 1 - 4126 ignitions
Range 2 - 217 ignitions
Range 3 - 28 ignitions
Range 4 - 48 ignitions

This Courtesy Inspection Completed By Your Porsche Service Team

Check Battery Condition

Good Recharge Bad

Comments: _____

Check Brakes

Measure Front / Rear Brake Linings

RF 8 7 RR

LF 8 7 LR

Over 5mm or 7/32"

3 to 5mm or 4/32" to 7/32"

Less than 3mm or 4/32"

Brake Measurements Not Taken This Service Visit

Comments: _____

Check Tires

TREAD DEPTH

LF 7/32" or Greater 4 5 7/32" or Greater

4/32" to 6/32" 7 7 4/32" to 6/32"

3/32" or Less 7 7 3/32" or Less

LR 7/32" or Greater 7 7 4/32" to 6/32"

4/32" to 6/32" 7 7 3/32" or Less

3/32" or Less 7 7 3/32" or Less

RR 7/32" or Greater 7 7 4/32" to 6/32"

4/32" to 6/32" 7 7 3/32" or Less

3/32" or Less 7 7 3/32" or Less

Wear Pattern / Damage RF

Tire Wear Indicators RR

Alignment Check Recommended Wheel Balance Recommended

Comments: _____

Service Advisor: _____

Technician: **Alec**

Customer Signature: _____

Tire Pressure Set to _____ PSI Front Rear

Untitled

Number of ignitions at speed > maximum speed, range 1 4126
Operating hours counter reading at overspeed, range 1
1838.14 h
Number of ignitions at speed > maximum speed, range 2 217
Operating hours counter reading at overspeed, range 2
1838.14 h
K040_Test counter for c.c. diagnosis b1 0
K050_Test counter for c.c. diagnosis b2 0
M120_Misfire counter for every ignition 63392
Number of ignitions at speed > maximum speed, range 3 28
Operating hours counter reading at overspeed, range 3
1650.29 h
Number of ignitions at speed > maximum speed, range 4 48
Operating hours counter reading at overspeed, range 4
1650.29 h
Number of ignitions at speed > maximum speed, range 5 0
Operating hours counter reading at overspeed, range 5 0.00 h

Number of ignitions at speed > maximum speed, range 6 0
Operating hours counter reading at overspeed, range 6 0.00 h

Operating hours counter 1880.16 h
Odometer 65890 km



RAY CATENA PORSCHE

123 SOUTH MAIN STREET
EDISON, N.J. 08837
732-205-9010
www.raycatena.com



0401IPOCS69839

CELL: 732-707-5555

CUSTOMER NO. 31110		ADVISOR CONOR	TAG NO. 94	INVOICE DATE 04/12/17	INVOICE NO. POCS69839
EURO PLUS 3713 ROUTE 1 NO. BRUNSWICK, NJ 08902		LABOR RATE 165.00	LICENSE NO.	MILEAGE 40,938	COLOR CARRARA WHI
		YEAR / MAKE / MODEL 11/PORSCHE/911 CARRERA GTS			DELIVERY DATE 09/29/11
EUROPLUSNJ@GMAIL.COM		VEHICLE I.D. NO. W P 0 A B 2 A 9 3 B S 7 2 1 1 0 5			SELLING DEALER NO.
		F.T.E. NO.			P.O. NO.
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS			
					MO: 40939

LABOR & PARTS-----
 J# 1 00POR0000 FLUIDS/PSI HOURS: 0.00 TECH(S):637 INTERNAL
 CHECK ALL FLUID LEVELS AND CHECK TIRE PSI
 TECH CHECKED AND TOPPED OFF ALL FLUID LEVELS AND CHECKED AND
 ADJUSTED ALL TIRE PSI
 COMPLETED

JOB # 1 TOTAL LABOR & PARTS 0.00

J# 2 00POZ-MISC1 INSPECT AND REPORT HOURS: 2.00 TECH(S):637 330.00
 CUST REQUEST FULL PPI
 TECH EVALUATION: OVER REV RANGE 4. RIGHT SIDE QUATER PANEL
 PAINTED. STEERING WHEEL OFF CENTER. VIBRATION ON HIGHWAY
 NO BENT RIMS POSSIBLE BALANCE. L/S WINDOW REGUALTOR NOISY
 BATTERY OK BUT NOT O.E. PERFORMED COMPRESSION TEST.
 1/280. 2/275. 3/275.
 4/280. 5/280. 6/290. ALSO SEE PREVIOUS PPI FOR MORE INFO

JOB # 2 TOTAL LABOR & PARTS 330.00

ESTIMATE-----
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$165.00 (+TAX)
 APPROVED REVISED ESTIMATE (# 1) OF \$350.00 (+TAX) ON 04/12/17 AT 04:26pm
 BY MR COMMENTS ALL DONE
 COMMENTS-----
 DROP

TOTALS-----

 * METHOD OF PAYMENT *
 * []CASH []CHECK *
 * []A/X []VISA *
 * []MASTER *
 * []RCMC CHARGE *

 TOTAL LABOR.... 330.00
 TOTAL PARTS.... 0.00
 TOTAL SUBLET... 0.00
 TOTAL G.O.G.... 0.00
 TOTAL MISC CHG. 0.00
 TOTAL MISC DISC 0.00
 TOTAL TAX..... 22.69

THANK YOU

TOTAL INVOICE \$ 352.69

CUSTOMER SIGNATURE
***** DUPLICATE INVOICE *****

The Reynolds and Reynolds Company ERANTINWE C0629432 Q (07/03)