

Warranty Information

92A, 970, 95B

D460

Replaces all previous bulletin bearing this number.

Timing Chain Cover Repairs

Model Line: Cayenne - V6T & V8 engine

Panamera - V6T & V8 engine

Macan - V6T engine

Model Year: 2011-2017

Information: If an oil leak is identified from the timing chain cover and it has been found that any part on the timing cover

has failed, then the engine must be removed and the entire timing chain cover resealed per the WM instruc-

tions.

Documentation Requirements



Active leak #1 overview of oil on engine




Warranty Information

92A, 970, 95B

D460

Information (continued):



Location and source of oil leak



A picture of the location and source of oil leak with engine clearly removed is required



Warranty Information

92A, 970, 95B

D460

Invoicing:

For invoicing and documentation using PCSS, the cause of failure must be encoded as follows:

Location (FES5)	15330	Chain Housing Cover
Damage Type	5043	Oil Leak

Suggested Labor Operations

Macan S:

10011940 - R&I engine

15331990 - R&I chain housing cover

87031750 - Refrigerant drain & fill

19381790 - Coolant drain and fill

44950300 - Alignment

44951553 - Alignment

46161902 - Remove brake-disc air guide

45600550 - Adjust steering angle sensor

27851550 - Adjust measuring sensor*

96382550 - Adjust front camera*

Macan GTS:

10011940 - R&I engine

15331990 - R&I chain housing cover

87031750 - Refrigerant drain & fill

19381790 - Coolant drain and fill

44950300 - Alignment

44951553 - Alignment

46161902 - Remove brake-disc air guide

45600550 - Adjust steering angle sensor

27851550 - Adjust measuring sensor*

96382550 - Adjust front camera*

Macan Turbo:

10011940 - R&I engine

15331990 - R&I chain housing cover

87031750 - Refrigerant drain & fill

19381790 - Coolant drain and fill

44950300 - Alignment

44951553 - Alignment

46161902 - Remove brake-disc air guide

45600550 - Adjust steering angle sensor

27851550 - Adjust measuring sensor*

96382550 - Adjust front camera*

Cavenne S:

10011940 - R&I Engine (without PDCC) **Or** 10011941 (with PDCC)

10012790 – Unflange Engine (without PDCC) Or 10012791 (with PDCC)

15331990 - Chain Housing Cover

87031750 - Refrigerant drained & filled

43030750 - PDCC Bled (with PDCC only)

44950300 - Alignment

44951553 - Alignment

^{*}If vehicle is equippled with respective option then additional labors may apply.