

VAL information » Summary

Vehicle status



Fault memory entries



10 Fault memory entries

Vehicle information



VIN	WP0AD29968S796307	Model type	911 (997)
Mileage	12688 km	Order type	997840
Transmission type	G9788	Date / time	25.07.2020 13:14:14
Engine number	0x26 2A	Operating time	292.800 h
Country code	USA	UI_VOLTAGE (Keine Übersetzung verfügbar)	12.3 V

VAL information » PIWIS Tester information

PIWIS Tester information details



VAL information » Fault codes

^ DME 997 Turbo +... fault code: P2181 ; P0461 ; ...

Software... Hardwar... 3

Test counter for c.c. diagnosis b1	0	
Test counter for c.c. diagnosis b2	0	
Engine start temperature	22.5 °C	
Calibration ID 1	99761867402	
Calibration ID 2		
CVN	0xDD 17 7B 36	
Ignition retard cylinder 1	0.00 °crk	
Retardation cylinder 6	0.00 °crk	
Retardation cylinder 2	0.00 °crk	
Ignition retard cylinder 4	0.00 °crk	
Ignition retard cylinder 3	0.00 °crk	
Retardation cylinder 5	0.00 °crk	
Ignition safety retardation	0	
Ignition map RON dependent	0.0	
Number of ignitions at speed > maximum speed, range 1	25765	
Number of ignitions at speed > maximum speed, range 2	8695	
Number of ignitions at speed > maximum speed, range 3	1916	
Number of ignitions at speed > maximum speed, range 4	159	7400 - 7900
Number of ignitions at speed > maximum speed, range 5	1	7900 - 9000
Number of ignitions at speed > maximum speed, range 6	0	
Operating hours counter reading at overspeed, range 1	255:900 h	

