



\*7405102718\*

Certificate Number

ONTARIO DRIVE CLEAN PROGRAM  
VEHICLE EMISSIONS INSPECTION REPORT

Test Date / Time: 2015-04-01 06:22 PM



ONTARIO MINISTRY OF THE ENVIRONMENT AND  
CLIMATE CHANGE

VEHICLE/ENGINE INFORMATION

Plate: 575RAX

Year: 1997

Cylinders: 6

VIN: WP0AA2996VS321874

Make: Porsche

Engine Size (L): 3.6

Type: Initial

Model: 911

GVWR (kg): 1693

OVERALL TEST RESULT: PASS

2 SPEED IDLE TAILPIPE EMISSIONS INSPECTION RESULTS

	2500 RPM			Idle		
	Limit	Reading	Result	Limit	Reading	Result
HC (ppm)	200	13	Pass	200	11	Pass
CO (%)	1	0.02	Pass	1	0.02	Pass
RPM	2250 - 2750	2440	Valid	< 1250	796	Valid
Dilution %	6	15.17	Valid	6	15.17	Valid

Thank you for making a positive contribution to the quality of our air by maintaining your vehicle and meeting vehicle emissions standards. Take this report with you when you renew registration and/or transfer ownership of your vehicle. A Drive Clean pass is valid for 12 months from its date of issue. For more information about Drive Clean, go to our website at [www.driveclean.com](http://www.driveclean.com) or call the Drive Clean Contact Centre at 1-888-758-2999.

Drive Clean is Ontario's mandatory vehicle emissions inspection and maintenance program. It improves our health and environment by reducing smog-causing pollutants through testing and repairing vehicle emissions systems.

What's good for your vehicle is good for everyone's lungs.

FOR PIO USE ONLY



\*8CUSLR9E5ZXCSJHVGJ5C\*

SECURITY CODE 2KRWYP

DRIVE CLEAN FACILITY

M & M Autobody Repair & Collision Centre Inc.  
2270 Kingston Road, Scarborough, ON, M1N1T9  
416-266-2229  
DCF #: 5595

Report Number: 3980  
Inspector ID: 902343  
Analyzer Number: A7405  
Software Version: 14.1.1.2

VEHICLE EMISSIONS INSPECTION QUESTIONS

Contact the Drive Clean Call Centre  
1-888-758-2999 [www.driveclean.com](http://www.driveclean.com)

Inspector's  
Signature:

mohammad Hajjani



\*7405102718\*

Certificate Number

ONTARIO DRIVE CLEAN PROGRAM  
VEHICLE EMISSIONS INSPECTION REPORT

Test Date / Time: 2015-04-01 06:22 PM



ONTARIO MINISTRY OF THE ENVIRONMENT AND  
CLIMATE CHANGE

VEHICLE/ENGINE INFORMATION

Plate: 575RAX

Year: 1997

Cylinders: 6

VIN: WP0AA2996VS321874

Make: Porsche

Engine Size (L): 3.6

Type: Initial

Model: 911

GVWR (kg): 1693

OVERALL TEST RESULT: PASS

2 SPEED IDLE TAILPIPE EMISSIONS INSPECTION RESULTS

	2500 RPM			Idle		
	Limit	Reading	Result	Limit	Reading	Result
HC (ppm)	200	13	Pass	200	11	Pass
CO (%)	1	0.02	Pass	1	0.02	Pass
RPM	2250 - 2750	2440	Valid	< 1250	796	Valid
Dilution %	6	15.17	Valid	6	15.17	Valid

Thank you for making a positive contribution to the quality of our air by maintaining your vehicle and meeting vehicle emissions standards. Take this report with you when you renew registration and/or transfer ownership of your vehicle. A Drive Clean pass is valid for 12 months from its date of issue. For more information about Drive Clean, go to our website at [www.driveclean.com](http://www.driveclean.com) or call the Drive Clean Contact Centre at 1-888-758-2999.

Drive Clean is Ontario's mandatory vehicle emissions inspection and maintenance program. It improves our health and environment by reducing smog-causing pollutants through testing and repairing vehicle emissions systems.

What's good for your vehicle is good for everyone's lungs.

FOR PIO USE ONLY



\*8CUSLR9E5ZXCSJHVGJ5C\*

SECURITY CODE 2KRWYP

DRIVE CLEAN FACILITY

M & M Autobody Repair & Collision Centre Inc.  
2270 Kingston Road, Scarborough, ON, M1N1T9  
416-266-2229  
DCF #: 5595

Report Number: 3980  
Inspector ID: 902343  
Analyzer Number: A7405  
Software Version: 14.1.1.2

VEHICLE EMISSIONS INSPECTION QUESTIONS

Contact the Drive Clean Call Centre  
1-888-758-2999 [www.driveclean.com](http://www.driveclean.com)

Inspector's  
Signature:

mohammad Hajjani